CURB & GUTTER

VALLEY GUTTER

VALLEY GUTTER TRANSITION

CONCRETE WATER TABLE

PREFABRICATED SIDEWALK DRAIN

CURB RAMP (NEW)

CURB RAMP W/DET WARNING SURFACE (NEW) 7A.

GRAVITY WALL ABOVE SIDEWALK

10. GRAVITY WALL BELOW SIDEWALK

11. HANDRAIL 11A ADA HANDRAIL

11A. ADA HANDRAIL

12. BRICK RADIUS CULVERT

13. PRECAST MANHOLE

14. NO. 7A MANHOLE RIM & COVER

15. NO. 7A ALT. MANHOLE RIM & COVER

16. NO. 10 INLET

17. NO. 10 RIM & GRATING (SEE 47)

18. NO. 11 INLET

19. NO. 11 RIM GRATING

20. NO. S-11 INLET

21. 6-72 INLET

22. TAPERED RIM GRATING FOR 6-72 INLET

23. TWIN 6-72 INLET

24. SPECIAL 3'x3' INLET

25. HEADWALL TYPE "A"

26. HEADWALL TYPE "B"

27. HEADWALL / SPILLWAY TYPE "C"

28. HEADWALL / WINGWALLS TYPE "D"

29. HEADWALL / WINGWALLS TYPE "E"

30. 3/16 INCH PER FOOT STRAIGHT SLOPE DETAIL

31. PARABOLIC CROWNS

32. REPAIR OF UTILITY CUTS

33. LIGHT STANDARD SUPPORT

34. CONSTRUCTION SIGN

34A. CONSTRUCTION SIGN WITH COUNCIL MEMBERS

35. TYPE III BARRICADE

36. CLOSING BASEMENT VENTS

37. DRAIN MANHOLE (BRICK)

38. RESIDENTIAL DRIVÈWAY

39. COMMERCIAL DRIVEWAY

40. CONVERSION OF INLET TO DRAIN MANHOLE

41. MINIMUM CURB ELEVATION

VERTICAL CURB

43. DITCH TO BOX CULVERT TRANSITION

44. VALLEY GUTTER INLET

45. RADIUS CURB CUT

46. 9-30 CURB AND TRANSMISSION

47. NO. 10 - NO. 3070 FRAME & GRATE

48. BRICK JUNCTION BOX

49. REINFORCED CONCRETE JUNCTION BOX

50. ALTERNATE RIM & GRATING FOR #10 INLET

51. ALTERNATE RIM & GRATING FOR #11 INLET

52. ALTERNATE RIM & GRATING FOR 6-72 INLET

53A. PAVEMENT REPAIR TRAVERSE PATCHES DETAIL

53B. PAVEMENT REPAIR WHEEL PATH DETAIL

53C. PAVEMENT REPAIR 53A. PAVEMENT REPAIR TRAVERSE PATCHES DETAILS

53E. PAVEMENT REPAIR PATCH INSIDE A PATCH DETAILS

53F. PAVEMENT REPAIR CUT RESTORATION DETAIL

53G. UTILITY CUT LOCATIONS AT INTERSECTIONS 53H. CONCRETE PAVEMENT REPAIR

531. PAVEMENT REPAIR PATCHES IN SERIES

DESIGN STANDARD

INDEX